

Asbestos Information for Contractors - Heath URC (subsequent to removal, cleansing and maintenance 2016)						
Floor	Room (see plan)	Site	Material	Asbestos type	Risk	Comment
2	Attic	/	/	/	/	No asbestos identified
1	Rm 08	Organ remains	Blower & switch	Chrysotile	6	presumed
0	Rm 01	Floor	Tile	Chrysotile	4	
0	Rm 01	Ceiling	Textured coating	Chrysotile	4	
0	Rm 02	Floor	Tile	Chrysotile	4	
0	Rm 03	Ceiling	Textured coating	Chrysotile	4	
0	Rm 04	Ceiling	Textured coating	Chrysotile	4	
0	Rm 05	Floor	Tile	Chrysotile	4	
0	Rm 05	Ceiling	Textured coating	Chrysotile	4	
0	Rm 06	Floor	Tile	Chrysotile	4	
0	Rm 06	Ceiling	Textured coating	Chrysotile	4	
0	Rm 07	Floor	Bitumen Adhesive	Chrysotile	4	
0	Rm 07	Ceiling	Textured coating	Chrysotile	4	
0	Rm 08	Floor	Tile	Chrysotile	4	
0	Rm 08	Ceiling	Textured coating	Chrysotile	4	
0	Rm 08	Door	Insulation Board	Amosite & Chrysolite	6	Encapsulated
0	Rm 09	/	/	/	/	
0	Rm 10	/	/	/	/	(cupboard - Amosite asbestos - removed 2016)
0	Rm 11	/	/	/	/	Insulation board - Amosite asbestos - removed 2016
0	Rm 12	/	/	/	/	
0	Rm 13	/	/	/	/	
0	Rm 14	/	/	/	/	
0	Rm 15	WC	Toilet cistern	Chrysotile	5	
0	Rm 16	/	/	/	/	
0	Exterior / Extension	Roof Eves	Cement Verge	Chrysotile	4	
0-1	Basement					Cement, insulation Board & debris - Chrysolite - removed 2016